## The following site is being submitted for inclusion into the GIS registry:

This is a:	New Submittal
BRRTS ID (no dashes):	0341001413 A + B
Comm # (no dashes):	53213422406
County:	Milwaukee
Region:	Commerce
Site name:	Total Gas Station
Street Address:	5706 W Bluemound Rd
City:	Milwaukee
Closure Date	2000-11-29
Closure Conditions:	met
Offsite contamination?	No
Right-of-way contamination?	No
Contaminated media:	Groundwater
GPS Coordinates (meters in the	e <b>WTM91</b> projection)
Easting (X):	684249.453291727
Northing (Y):	286861.513256658
Submitted by:	Cheryl Nelson

## Checklist

 $\boxtimes$ Final Closure Letter Copy of recorded deed Instrument for any property with GW >NR140 ES  $\boxtimes$ General Location Map  $\boxtimes$ Detailed Location Map showing property boundaries, buildings, etc for properties with GW  $\boxtimes$ >NR140 ES Latest Map(s) showing extent or outline of current GW plume  $\boxtimes$ GW flow direction MW(s) and/or potable wells  $\boxtimes$  $\boxtimes$ Latest Table of GW results



ENVIRONMENTAL & REGULATORY SERVICES
101 West Pleasant Street, Suite 205
Milwaukee, Wisconsin 53212
Fax: (414) 220-5374
TDD #: (608) 264-8777
www.commerce.state.wi.us
Tommy G. Thompson, Governor
Brenda J. Blanchard, Secretary

November 29, 2000

Ms. Alexis Smith 15055 West Lincoln Avenue New Berlin, WI 53151

RE:

COMMERCE # 53213-4224-06-A and -B

Total Gas Station, 5706 West Bluemound Road, Milwaukee, WI Gasoline Underground Storage Tanks removed in 1994

Case Closure

Dear Ms. Smith:

On October 27, 2000, the Department received copies of the monitoring well and sump abandonment forms. On November 28, 2000, the Department received a notarized copy of the *Notice of Contamination to Property* that was recorded for the referenced property. Therefore, this site is now listed as "closed" on the Commerce database.

Please note that there are two Commerce occurrences (A and B) and two PECFA claims for this site. However, there has only been one case file with one WDNR BRRTS number for this site. This letter serves to close both occurrences.

Thank you for your efforts in the protection of Wisconsin's environment. If you have any questions, feel free to contact me at (414) 220-5376.

Sincerely,

Em

Linda M. Michalets Hydrogeologist Site Review Section

cc:

Mr. Terry Baker, Baker Enterprises (via facsimile) Mr. Jeffrey M. Larkin, Moraine Environmental, Inc. Commerce electronic file NOTICE OF CONTAMINATION TO PROPERTY

REGISTER'S OFFICE | SS Milwaukee County, WI!

7994006

RECORDED AT 12:28 PM

11-27-2000

WALTER R. BARCZAK REGISTER OF DEEDS

AMOUNT 16.00

Legal Description of the Property: In Re: 5706 W. Bluemound Road, Milwaukee, Wisconsin

The property described as; LANDS IN SW 1/4 SEC 26-7-21 COM INTER OF ELY LI N HAWLEY RD & NLY LI W BLUE MOUND RD-TH N 11DEG 36MIN 05SEC E 98 .12' - TH N 9DEG 37MIN 50SEC E 44 . 60' TH E 121.41' - TH S 150' - TH NWLY 134' - TH N 54DEG 49MIN 03SEC W 17.12' TO BEG

STATE OF WISCONSIN ) ss COUNTY OF MILWAUKEE )

## RECEIVED

NOV 28 2000 PECFA SITE REVIEW MILWAUKEE OFFICE Name and Return Address
Ms. Alexis Smith
15055 W. Lincoln Avenue
New Berlin, Wisconsin 53151

404 - 9978 - 120 - 4

Parcel Identification No. (PIN)

Ms. Alex Smith is the owner of the above-described property.

One or more petroleum discharges have occurred at this property. Benzene and Trimethylbenzenes contaminated groundwater, above NR 140 Enforcement Standards and Benzene, Ethylbenzene, Xylene and Total Lead contaminated soils above NR 720 Residual Contaminant Levels of the Wisconsin Administrative Code, exist (s) on this property. See Figures 1 and 2 for approximate contaminant locations.

The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

Also,

Residual petroleum contaminated soil remains on this site. Natural attenuation is the approved remedial alternative for this site. If contaminated soil is excavated in the future, it may be considered a solid waste and will need to be disposed of in accordance with all applicable laws.


Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site

specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an
affidavit with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of
this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's
written determination.


IN WITNESS WHEREOF, the owner of the property has executed this document, this <u>~</u> day o <u>0 ついい</u> ,20 <u>り</u>	if
Signature: <u>Aleps Smith</u> Baker	
Printed Name: Alexis Smith	
Title: Owner	
Subscribed and sworn to before me this 3 day of October, 2000.	
Notary Public, State of Wisc	


This document was drafted by the Wisconsin Department of Commerce.

E:\WORD\MSWTECH3\0335deed not..doc



Moraine Environmental, Inc. Environmental Management Services	FIGURE 1
SITE LOCATION MAP	
BAKER ENTERPRISES 5706 West Bluemound Road Milwaukee, Wisconsin	





											SROI	NON	VATE	GROUNDWATER QUALITY RESULTS	ALE	IYR	ESCI	<b>2</b> E													
												HA	WLE	HAWLEY ROAD PUMP	ADF	UMD															
										5706	%. BI	NEW	NJ0	W. BLUEMOUND ROAD, MILWAUKEE, WI	AD,	MILV	VAUI	ŒE,	130						Ì						
		MW-1	V-1				MW-2	-2		MW-3	7-3		R	RW-3				SVE-3	3-3				RW-1				R	RW-2			NR140
Analyte	16/67,1	2/94 1/15	1/98 4/1	472991 67294 1/13/98 4/10/98 7/14/99 4/25/91 6/2/94 1/13/98 4/10/98 7/14/99	9 4/29/5	11 6/2/9.	4 1/13/98	3 4/10/98	7/14/99	4/29/91	6/2/94 4	4/29/91 6	17 17	62294 17.13.98 47.10,98 77.14.99 47.29.91 67.294 47.10.98 77.14.99 47.29.91 67.294 17.13.98 47.10.98 77.14.99	0/98 7/14	1/99 4/29,	191 6/2/9	94 1/13,	98 4/10/5	.8 7/14/9.	9 4/29/91	6/2/94	1/13/98	4/10/98	7/14/99 4	16/67/1	7,2/94 1/	13/98 4/1	.1// 86/0		ES PAL
Gasoline Range Organics	*	<\$0	* 0\$>	* * * *	*	1200	- 0	280	*	*	<50	*	*	¥ 0\$>	*	*	*	*	* 120	*	*	*	* *	0\$>	*	*	*	**	0\$>	ž *	NSE NSE
Diesel Range Organics	*	<100 <100	<del> </del>	*	*	270		*	*	*	001>	*	*	1500	*	*	*	*	*	*	*	*	*	*	*	*	*	* *	*	*	NSE NSE
Soluble Lead	*	<1.0 <1.5	<del> </del>	*	*	0.1	-	*	*	*	<1.0	*	*	4.5	* * *	*	*	*	*	*	*	*	*	*	*	*	*	* *	*	* 15	5 1.5
Benzene	<1.0	<0.6 <0.41		*** <0.26	9 <b>091</b>	67 6	-	<0.26	43	<1.0	9:0>	*	*	<0.41	*** <0.26	26 **	*	*	<0.26	6 <0.26	*	*	* *	<0.26	<0.26	*	*	*** 1	1.0 8.7	7 5.0	0 0.5
Ethyl Benzene	<1.0	<1.0 <0.23		*** <0.24	4 160	82	1	<0.24	80	<1.0	<1.0	*	*	<0.23	*** <0.24	24 **	*	***	* 2.3	5.1	*	*	***	<0.24	<0.24	*	*	0>  ***	<0.24 <0.24	24 700	0 140
Isopropylbenzene	*	<1.0 <0.27	27 ***	*	*	2.7	1	*	*	*	<1.0	*	*	<0.27	* ***	*	*	*	*	*	*	*	***	*	*	*	*	**	*	NSE	E NSE
Methylene Chloride	*	<4.0 <0.22	22 ***	*	*	<4.0	-	*	*	*	<4.0	*	*	0.35 **	*	*	*	*	*	*	*	*	*	*	*	*	*	* *	*	5.0	0 0.5
Methyl - Tert - Butyl Ether	*	4.3 3.3	***	* 2.3	*	8	1	<0.22	12	*	49	*	*	2.0	*** 3.3	3 **	*	*	<0.22	2 <0.22	*	*	***	<0.22	1.2	*	*	0> ***	<0.22 2.7	09 /	12
n-Propylbenzene	*	<1.0 <0.27	27 ***	*	*	5.8	ı	*	*	*	<1.0	*	*	<0.27	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	NSE	E NSE
Toluene	> 0.1>	<1.0 <0.28	78 ***	* <0.21	1,700	29	!	<0.21	4.0	<1.0	<1.0	*	*	<0.28	*** <0.21	21 **	*	*	\$ 0.65	0.52	*	*	*	0.34	<0.21	*	*	***	0.54 0.57	7 343	3 68.6
Trimethylbenzenes	*	<1.0 <0.30	30 ***	* <0.86	*	120	-	1.4	1,020	*	<1.0	*	0	0.32	98:0>	** 98	*	*	1.8	2.0	*	*	*	<0.86	>0.86	*	*	0> ***	>0.86 <0.86	86 480	96 0
Xylenes (m,p, o)	0.1>	<1.0 <0.79	*** 62	× <0.97	4100	130	ł	<1.34	009	<1.0	<1.0	*	*	** 67.0>	*** <0.97	** 16	*	*	0.74	2.86	*	*	*	<1.34 <0.97	76:0>	*	*	!> **	<1.34 <0.97	97 620	0 124
ES = Enforcement Standard PAL = Preventive Action Limit - = Monitoring Well Dry ** = Well not yet installed. Shaded box with bold print indicates exceedence of NR 140 ES	ent Stand e Action   ig Well D et installe	ard Limit ry ed.	ecede	nce of NR	140 ES				* = NSE = *** = *** All result Print Bold Pr	NSE = Not Analyzed     NSE = No Sandard Established     *** = Not Sampled All results are expressed in microgramsfilter. Bold Print alone indicates exceedence of NR	alyzed lard Esta sled messed in	blished 1 microg exceeder	ams/lite	NSE = Not Analyzed     NSE = No Standard Established     NST = Stangled     NSE = Stangled     NSE = Not Sampled     NSE = Stangled     NSE =	3																